

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Torrance, CA 90502			A.State Manifest Document Number 84924321				
4. Generator's Phone (213 533-6677)			B.State Generator's ID				
5. Transporter 1 Company Name Oil Process Co.		6. US EPA ID Number C A D 0 5 0 8 0 6 8 5 0		C.State Transporter's ID 63695			
7. Transporter 2 Company Name		8. US EPA ID Number		D.Transporter's Phone 213 535-5063			
9. Designated Facility Name and Site Address Demmonno Kerdoon 2000 N. Alameda Compton, CA 90022		10. US EPA ID Number C A T 0 8 0 0 1 3 3 5 2		E.State Transporter's ID			
				F.Transporter's Phone			
				G.State Facility's ID			
				H.Facility's Phone 0800 13352			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12.Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Hazardous Waste Liquid NOS ORM-E NA9189			001	TT	4500	G	221
b.							
c.							
d.							
J. Additional Descriptions for Materials Listed Above Bio-Degradable Coolant 15% Tramp Oil 35% Water 50%			K.Handling Codes for Wastes Listed Above 01				
15. Special Handling Instructions and Additional Information Guide #31 Use gloves, goggles, respirator - Do not go near open flame or inhale fumes.							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.							
Printed/Typed Name Donald C. Gerber			Signature <i>Donald C. Gerber</i>		Date Month Day Year 03 17 86		
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>John Neal</i>		Date Month Day Year 3 17 86		
Printed/Typed Name S-D-35347 JOHN NEAL							
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date Month Day Year		
Printed/Typed Name							
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name William			Signature <i>William</i>		Date Month Day Year 13 17 86		

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Torrance, CA 90502			A.State Manifest Document Number 84924321		B.State Generator's ID	
4. Generator's Phone (213 533-6677)		6. US EPA ID Number C A D 0 5 0 8 0 6 8 5 0		C.State Transporter's ID 63615		
5. Transporter 1 Company Name Oil Process Co.		8. US EPA ID Number		D.Transporter's Phone 213 585-5063		
7. Transporter 2 Company Name		10. US EPA ID Number		E.State Transporter's ID		
9. Designated Facility Name and Site Address Demanno Kerdoon 2000 N. Alameda Compton, CA 90022			F.Transporter's Phone		G.State Facility's ID	
			H.Facility's Phone			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12.Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. Hazardous Waste Liquid NOS ORM-E NA9189			001	TT	4,500	G
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above Bio-Degradable Coolant 15% Tramp Oil 35% Water 50%			K.Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Guide #31 Use gloves, goggles, respirator - Do not go near open flame or inhale fumes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature <i>Donald C. Gerber</i>		Date Month Day Year 03 17 86	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>John Neal</i>		Date Month Day Year 03 17 86	
Printed/Typed Name S-D-35347 JOHN NEAL			Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date	
Printed/Typed Name			Signature		Date	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name			Signature		Date Month Day Year	